

# TERMOMETRE

Fara carcasa



Parametrii tehnici	TM-14/1	TM-19/1	TM-14/2	TM-19/2
Diapazon de masurare, V	-50... +125, pasul :1		-19,9... +99.9, pasul :0,1	
Gradatia de afisare, °C	1		0,1	
Eroare de masurare, %, nu mai mult de	0,5		0,5	
Tensiunea de alimentare, V (DC)	8 - 15		8-15	
Dimensiunea indicatorului, mm	14x25	19x40	14x25	19x40